











-10°C ... +70°C	-5°C ... +40°C			
P	U, f		250 V~ 8 A, cos φ = 1 2 A, cos φ = 0,6	6 mm 1,5..4 mm² 1,5..2,5 mm²
< 1 W	230 V~ 50 / 60 Hz	10°C ... 30°C $\Delta K = \pm 2K$		









			ΔK
-10°C ... +70°C	-5°C ... +40°C	 1 ... 6 (10°C...60°C)	± 2K

			P	U
≤ 20 m	250 V~ 16 A, cos φ = 1	6 mm 1,5..4 mm ² 1,5..2,5 mm ²	< 1 W	230 V~ 50 / 60 Hz



Load



Temperature sensor

